

Registration Schedule

| Branch | Address |
|----------------------|---|
| On-Wood Products Ltd | Unit 1 Wealdhall Farm Canes Lane North Weald, Epping Essex, CM17 9LD |

Scope

Primary Field of Application (FoA) Reports (owned by this certified company)

Primary FoA reports owned by this Q-Mark certified company are listed on the Q-Mark certificate along with the latest revision status. They are either used in isolation, or can be used in conjunction with an appropriate associated document that is listed below, providing that the FoA report allows it and that both documents are compatible with each other. Where more than one primary FoA is listed for the same doorset type, they cannot be mix and matched, only one FoA is to be chosen and followed precisely.

| FoA Report | Rev | Owned by Certified Company named on this scope | Doorset Description | Rating | Test Type |
|------------|-----|--|---------------------|--------|-----------|
| NONE | - | - | - | - | - |

Primary Field of Application Reports (owned by and cascaded by a System Supplier)

Primary FoA reports owned by a System Supplier are listed on the Q-Mark certificate. The revision status of each FoA can be verified on the BM TRADA website under each System Supplier's certification entry. They are either used in isolation, or can be used in conjunction with an appropriate associated document that is listed below, providing that the FoA report allows it and that both documents are compatible with each other.

Where more than one primary FoA is listed for the same doorset type, they cannot be mix and matched, only one FoA is to be chosen and followed precisely.

| FoA Report | System Supplier owner of Assessment Report | Doorset Description | Rating | Test Type |
|----------------|--|--|--------|---------------|
| Chilt/A01204 | Halspan Limited | Optima 30 (Glazed or unglazed) | 30min | BS476 Part 22 |
| Chilt/A01205 | Halspan Limited | Optima 60 (Glazed or unglazed) | 60min | BS476 Part 22 |
| FEA/F97174 | Halspan Limited | Prima 30 (Glazed or unglazed) | 30min | BS476 Part 22 |
| FEA/F97174 | Halspan Limited | Prima Plus 30 (Glazed or unglazed) | 30min | BS476 Part 22 |
| FEA/F96103 | Halspan Limited | Prima 60 (Glazed or unglazed) | 60min | BS476 Part 22 |
| FEA/F96103 | Halspan Limited | Prima Plus 60 (Glazed or unglazed) | 60min | BS476 Part 22 |
| FEA/F97097 | Halspan Limited | Prima 30 Panelled(Glazed or unglazed) | 30min | BS476 Part 22 |
| Chilt/A01015 | Halspan Limited | Prima 60 Panelled(Glazed or unglazed) | 60min | BS476 Part 22 |
| Chilt/A05151 | Halspan Limited | Halspan 90 (Glazed or unglazed) | 90min | BS476 Part 22 |
| BMT/CNA/F15082 | Halspan Limited | Halspan 120 (Glazed or unglazed) | 120min | BS476 Part 22 |
| WF389581 | Halspan Limited | Halspan 90 Prima Plus (Glazed or unglazed) | 90min | BS476 Part 22 |
| WF389580 | Halspan Limited | Halspan 120 Prima Plus (Unglazed) | 120min | BS476 Part 22 |
| Chilt/A12137 | Falcon Panel Products Ltd | Strebord® 35 Doorsets(Glazed or Unglazed) | 30min | BS476 Part 22 |
| WF380559 | Falcon Panel Products Ltd | Strebord® 35+ Doorsets(Glazed or Unglazed) | 30min | BS476 Part 22 |
| WF380559 | Falcon Panel Products Ltd | Strebord® 38+ Doorsets(Glazed or Unglazed) | 30min | BS476 Part 22 |
| Chilt/A02066 | Falcon Panel Products Ltd | Strebord® 44 Doorsets (Strebord® 44 blank only) (Glazed or Unglazed) | 30min | BS476 Part 22 |
| Chilt/A09104 | Falcon Panel Products Ltd | Strebord® 44 Panelled Doorsets(Glazed or Unglazed) | 30min | BS476 Part 22 |
| Chilt/A02067 | Falcon Panel Products Ltd | Strebord® 54 Doorsets (Glazed or Unglazed) | 60min | BS476 Part 22 |
| Chilt/A10152 | Falcon Panel Products Ltd | Strebord® 54 Panelled Doorsets(Glazed or Unglazed) | 60min | BS476 Part 22 |
| Chilt/A12138 | Falcon Panel Products Ltd | 60 minute Fire Resisting Doorsets(Glazed or unglazed) | 60min | BS476 Part 22 |
| Chilt/A12138 | Falcon Panel Products Ltd | 90 minute Fire Resisting Doorsets(Glazed or unglazed) | 90min | BS476 Part 22 |
| Chilt/A12138 | Falcon Panel Products Ltd | 120 minute Fire Resisting Doorsets(Glazed or unglazed) | 120min | BS476 Part 22 |
| WF407090 | Falcon Panel Products Ltd | Strebord® 44 30 minute Front Entrance Doorsets (Glazed or Unglazed) | 30min | BS476 Part 22 |
| WF407090 | Falcon Panel Products Ltd | Strebord® 54 30 minute Front Entrance Doorsets (Glazed or Unglazed) | 30min | BS476 Part 22 |
| WF407090 | Falcon Panel Products Ltd | Stredor® 44 30 minute Front Entrance Doorsets(Glazed or Unglazed) | 30min | BS476 Part 22 |
| WF407090 | Falcon Panel Products Ltd | Stredor® 54 30 minute Front Entrance Doorsets(Glazed or Unglazed) | 30min | BS476 Part 22 |
| Chilt/A13058 | Moralt AG | LAMINESSE FireSafe and FireSmoke 44mm (Glazed or unglazed) | 30min | BS476 Part 22 |
| Chilt/A13059 | Moralt AG | LAMINESSE FireSafe and FireSmoke 54mm (Glazed or unglazed) | 60min | BS476 Part 22 |
| WF409922 | Moralt AG | LAMINESSE FireSound 54mm(Glazed and Unglazed) | 30min | BS476 Part 22 |
| WF409922 | Moralt AG | LAMINESSE FireSound 54mm(Glazed and Unglazed) | 60min | BS476 Part 22 |
| BMT/CNA/F14274 | Moralt AG | LAMINESSE FireSound 44mm (Glazed or unglazed) | 30min | BS476 Part 22 |
| WF409923 | Moralt AG | LAMINESSE FireSound 59mm(Glazed and Unglazed) | 30min | BS476 Part 22 |
| WF409923 | Moralt AG | LAMINESSE FireSound 59mm(Glazed and Unglazed) | 60min | BS476 Part 22 |
| FEA/F98164 | Pacific Rim Wood Ltd | Flamebreak 30 (Glazed or unglazed) | 30min | BS476 Part 22 |
| FEA/F02141 | Pacific Rim Wood Ltd | Flamebreak 60 (Glazed or unglazed) | 60min | BS476 Part 22 |

Winkhaus Reports – cannot be used in conjunction with any ‘Associated Documents’ noted below

| Assessment/ Test Report | Owner of Assessment/ Report | Doorset Description | Rating | Test Type |
|-------------------------|-----------------------------|---|----------------|-------------|
| BMT/CNA/F15084 | Winkhaus UK Ltd | Winkhaus Timber Frame with Halspan Blank (Glazed or unglazed) | 30min 60min | BSEN 1634-1 |

| Assessment/ Test Report | Owner of Assessment/ Report | Doorset Description | Rating | Test Type |
|-------------------------|-----------------------------|---|----------------|-------------|
| BMT/CNA/F15084 | Winkhaus UK Ltd | Winkhaus Timber Frame with Halspan Blank (Door leaf Only) | 30min 60min | BSEN 1634-1 |

Please note only approved Q-mark manufactures holding BMT/CNA/F15084 under their ‘Fire Door Manufacturing’ certificate and holding dual Q-Mark ‘Security & Fire’ certification under the PAS24 scheme can be supplied with the door leaves only as detailed above

Test Reports

Test reports are listed on the Q-Mark certificate. They cannot be used in conjunction with any primary FoA reports, other test reports or associated documents. They must be followed precisely without any deviation whatsoever.

No specification or parameter changes are allowed at all from that stated within the test report such as size, shape, design, glazing, leaf/frame specification, hardware etc.

| Test Report | Owner of Test Report | Doorset Description | Rating | Test Type |
|-------------|----------------------|---------------------|--------|-----------|
| NONE | - | - | - | - |

Associated documents

Associated documents are not shown on a Q-Mark certificate. They are only to be used in conjunction with any appropriate primary FoA reports listed above. Any doorset configuration or size parameters etc. stated in the primary FoA reports listed above shall take priority unless otherwise specifically stated in the associated document.